


ACCEPTABLE CONDITION  
(AS DELIVERED)



UNACCEPTABLE CONDITION  
(AS DELIVERED)

NOTE:  
A ROOT COLLAR EXCAVATION FOR ALL TREES SPECIFIED WILL BE INSPECTED BY THE INSPECTOR TO ENSURE THAT TREES WERE NOT PLANTED/GROWN TOO DEEPLY AT SOURCE (NURSERY). LANDSCAPE CONTRACTOR SHALL HAVE SUPPLIER MARK GROUND LEVEL LINE ABOVE ROOT BALL. IF INSPECTOR DETERMINES THAT THERE IS EXCESSIVE SOIL OVER THE ROOT CROWN, THESE TREES WILL BE REJECTED.

NOT TO SCALE